

*BEST COPY*

*AVAILABLE*

*For all of these :*

*THRU OUT FOLDER*

2961 E. COLORADO ST., PASADENA, CALIF.

RECEIVED FROM

DATE RECEIVED 3-16-57

P.O. NO.

VENDOR PACKING SLIP NO.

W.O. NO.

Q.A. NO.

CONTRACT CODE NO.	DRAWING NUMBER	DWG. PART OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	QTR. NUMBER
322	0	025	0	40		

CHANGE TO QUANTITY RECEIVED

DRAWING NO. AND DESCRIPTION

ACCEPTED

REJECTED

MARK

50

7745

Resistor Hammer Post

50

ISS 707747

*[Handwritten signature]*

*[Circular stamp]*

RECEIVED BY *[Signature]*

INSPECTED BY

009 3/16/57

REJECTS RETURNED ON QTR. MEMO NO.

RECEIVING INSPECTION REPORT

HYCON MFG. COMPANY

2961 E. COLORADO ST., PASADENA, CALIF.

No. 15595

RECEIVED FROM

DATE RECEIVED 3-16-57

P.O. NO.

VENDOR PACKING SLIP NO.

W.O. NO.

Q.A. NO.

CONTRACT CODE NO.	DRAWING NUMBER	DWG. PART OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	QTR. NUMBER
322	00000	266	0	20		

CHANGE TO QUANTITY RECEIVED

DRAWING NO. AND DESCRIPTION

QUANTITY

ACCEPTED

REJECTED

MARK

2

737439

Spring Assembly

2

ISS 707355

*[Handwritten signature]*

RECEIVED BY *[Signature]*

INSPECTED BY

DATE

009 3/16/57

REJECTS RETURNED ON QTR. MEMO NO.